Case Report

Huge calf swelling associated with a failed total knee replacement: A case report

Muhammed Nazeer^{1,*}, Rohith Raveendran¹, Bharat C Katragadda¹,
Muhammed Ehsan N²

¹Dept. of Orthopedics, Kerala Institute of Medical Sciences, Thiruvananthapuram, Kerala, India

²Dept. of Orthopedics, Kasturba Medical College, Mangalore, Karnataka, India

ARTICLE INFO

Article history:

Received 18-06-2020

Accepted 23-06-2020

Available online 19-09-2020

Keywords:

Calf

Loosening

Polyethylene wear

Revision

Synovial cyst

Total knee arthroplasty

ABSTRACT

Introduction: In patients who have undergone a total knee arthroplasty (TKA), any swelling occurring in or adjacent to the joint needs thorough investigation and a wear debris-induced cyst or pseudotumor should be suspected.

Case History: A 75-year-old man, who underwent primary TKA for osteoarthritis three years back, presented with a swelling in the popliteal fossa extending into calf region of his left knee. Radiographs showed medial space narrowing, component loosening and osteolysis. Magnetic resonance imaging showed a popliteal cyst communicating with the knee joint and extending into the calf. A two stage procedure was done, excision of cyst followed by revision TKA after three weeks. At one year follow-up, the patient had a painless knee without cyst recurrence.

Conclusion: Long term follow-up is critical for patients with TKA for early detection of occult polyethylene wear and prosthesis loosening. Joint effusion and synovial cyst formation should be considered a preceding sign of periprosthetic osteolysis.

© 2020 Published by Innovative Publication. This is an open access article under the CC BY-NC license (<https://creativecommons.org/licenses/by-nc/4.0/>)

1. Introduction

In patients with total knee arthroplasty (TKA), any mass occurring in and around the knee joint needs thorough assessment. The differential diagnosis include hematoma, infection, Morant-Baker's cyst, ganglion cyst, semimembranosus bursitis, popliteal artery aneurysm, primary soft tissue or bone tumors, thrombophlebitis, cellulitis and deep vein thrombosis. In post knee arthroplasty scenario, pseudotumor mass or a wear debris induced cyst, should also be considered. Characteristic findings on physical examination as well as radiologic and serologic examinations can make the diagnosis straightforward in most of the cases. We report a case of failed TKA that presented as a cystic swelling in the calf region without much knee symptoms, three years after primary TKA.

2. Case Report

A 75 year old male patient presented to us with complaints of a progressively enlarging swelling in his left calf region of three months duration. He had undergone left total knee arthroplasty (posterior stabilized, Exactech Optetrak prosthesis, Florida, USA) for tricompartmental osteoarthritis three years back (Figure 1). Three months ago, the patient noticed a small mass developing around his popliteal fossa with intermittent swelling of the knee joint. There was a progressive increase in size of the swelling. He experienced restriction in knee movements in the last one month following which he presented to us for evaluation. There were no constitutional symptoms.

On examination, there was a 20cm x 10 cm soft tissue swelling extending from popliteal fossa to the mid calf region of the left leg (Figure 2). The swelling was cystic with a smooth surface, non tender and non-pulsatile. Mild effusion was noted in the left knee joint without any

* Corresponding author.

E-mail address: drmuhammednazeer@gmail.com (M. Nazeer).

signs of inflammation. Active knee range of motion was limited to 50° - 90°, with normal distal neurovascular status. Radiographs showed loss of joint space mainly on the medial side between the femoral and tibial components, periprosthetic osteolysis of the distal femur and a large soft tissue shadow in the popliteal and calf area (Figure 3). A doppler ultrasound scan ruled out deep vein thrombosis. An MRI scan revealed a large cystic mass of size 18cm x 9cm x 7cm expanding from the gastrocnemius-semimembranosus bursa and extending into the calf between the gastrocnemius and soleus muscles (Figure 4). Blood investigation showed a normal white blood cell count (TC=5000/ mm³), normal erythrocyte sedimentation rate (ESR= 5mm/hr) and C-reactive protein (CRP= 0.3mg/L) levels. The coagulation parameters were within normal limits. With the presumptive diagnosis of polyethylene lysis and aseptic loosening of femoral component associated with a calf mass, the plan was to proceed with a two stage procedure- 1) excision of swelling with microbiologic and histopathologic examination, followed by 2) definitive procedure after getting the lab reports.

The cystic mass was approached through a posteromedial approach. Per-operatively, the cystic mass was communicating with the posteromedial knee joint (Figure 5). The mass was excised and it contained around 1000ml thick yellow fluid with polyethylene debris and necrotic material (Figure 6). Microbiological evaluation was negative and histopathologic examination showed multinucleated foreign body giant cells around refractile material without atypia, consistent with the picture of a tissue response to artificial joint implants (Figure 7).

After having an uneventful soft tissue healing, revision knee arthroplasty was performed through a medial parapatellar approach. Peroperatively there was extensive synovial hypertrophy without any metallosis (Figure 8). The polyethylene insert had gross pitting and delamination along with tibial post wear and backside wear (Figure 9). After extensive synovectomy, loosened femoral and tibial components were carefully removed. Extensive bone loss along with loss of integrity of medial collateral ligament was noted on the femoral side (Figure 10), for which a Distal femoral replacement component (LPS, Depuy Orthopedics, Warsaw, USA) was used and the tibial side bone defect needed a metaphyseal sleeve and stem with a MBT revision tray (Figure 11). There was uneventful postoperative recovery. At one year follow-up, there was pain free joint movements with range of 0°–110°. There were no signs of cyst recurrence.

3. Discussion

A leading cause of total knee arthroplasty (TKA) failure is attributed to aseptic loosening from polyethylene wear disease. Mechanical wear patterns of the implanted high-molecular weight polyethylene (UHMWPE) include pitting,

Fig. 1: Radiographs of primary TKA, taken 3 years back

Fig. 2: Clinical photographs of left leg showing a huge swelling in the popliteal and calf region

Fig. 3: Pre-operative radiographs show loss of joint space between femoral and tibial components, periprosthetic osteolysis on both distal femur and proximal tibia, along with a soft tissue mass shadow in the posteromedial aspect

Fig. 4: MRI images of the left leg showing large cystic mass extending from popliteal fossa to midcalf, communicating with the knee joint

Fig. 5: Intraoperative photograph after excision of the cystic mass showing plane between the medial gastrocnemius and semimembranosus

Fig. 6: Image showing (a): Cystic mass (18cmx9cmx7cm) excised from the leg, and (b): Turbid fluid containing coarse granules evacuated from the cystic mass

Fig. 7: Histo-pathologic section shows a foreign body reaction with giant cells around refractile material

Fig. 8: Intraoperative clinical photograph during revision TKA showing hypertrophied synovium

Fig. 9: Photograph of delaminated, worn polyethylene insert

Fig. 10: Intra-operative photograph after extraction of components showing extensive osteolysis of femoral condyles

Fig. 11: Radiograph of left knee after revision TKA

Fig. 12: Radiograph of left knee at one year follow-up

scratching, burnishing, abrasion and delamination, which can all liberate numerous fine polyethylene particles. This wear debris induces macrophage phagocytosis that triggers an inflammatory reaction within the knee joint which can lead to synovitis, repeat effusions and ultimately, to aseptic loosening.

In this setting, pain and swelling of the knee joint are usually the most common presenting symptoms. However, atypical manifestations such as a popliteal cyst, bursitis, calf mass, or thigh mass can be the presenting symptom, making the initial diagnosis difficult. Dissecting popliteal cyst associated with failed TKA was reported by Dirschl et al,¹ Moretti et al,² Niki et al,³ Chan et al⁴ and Tofte et al.⁵ Failed TKA presenting with calf mass was reported by Akisue et al,⁶ Chang et al⁷ and Choi et al.⁸ Bursitis and thigh mass due to polyethylene wear disease were reported by Huang et al⁹ and Chavda et al¹⁰ respectively. These masses have been reported two to eight years following the primary joint replacement. In all cases, as in our case, the final diagnosis was foreign body reaction due to polyethylene or metal wear debris.

The high intraarticular pressure caused by particle-induced joint effusion contributes to a popliteal cyst formation. Pseudotumor like mass may be formed due to a granulomatous inflammatory reaction to excessive wear particles generated. Fluid pressure arising from the joint allows the particles to track along soft tissue planes giving rise to a gradually enlarging mass somewhat distant from the joint. These masses may attain large size causing pressure symptoms. In the present case, synovial fluid with polyethylene wear particles from the joint, drained underneath the fascia and the medial head of the gastrocnemius muscle in the popliteal fossa and

progressively enlarged into the calf region with increased wear particle generation.

The factors that influence implant wear include: patient factors (age, activity and weight), implant factors (type of articulation, design, bearing surfaces, polyethylene thickness and method of sterilization), and surgical factors (alignment and ligament balancing). Any combination of these factors may result in the generation of significant quantities of particulate debris. In the reports reviewed, the causes for wear generation were- young age, high activity level,^{6,8} thin polyethylene insert(<8mm), polyethylene oxidation⁶ and malaligned tibial tray. In our case, lack of regular follow-up led to the delay in the diagnosis, ultimately contributing to the formation of a huge mass and extensive osteolysis. The paucity of subjective symptoms such as pain and minimal knee effusion obscured the clinical picture.

In terms of treatment for failed TKA with the symptom of an extraarticular mass, single stage or a two-stage revision was recommended by different authors with good results. Niki et al³ advocated synovectomy and polyethylene liner exchange in a patient with implant well positioned and well fixed. Dirschl et al¹ reported about three patients who underwent a revision of TKA without excision of the popliteal cyst. Chan et al⁴ was the first to advocate a two-stage procedure for the treatment of a large dissecting popliteal cyst after failed TKA, cyst excision in the first stage followed by revision TKA after few weeks. The rationale behind this management was to first relieve the pain caused by large cyst, and also eliminate the polyethylene debris-induced factor causing osteolysis and prosthesis loosening. Moretti et al² also recommended a two stage procedure with a long-term interval of five months between the stages in case of very old patients, particularly those with medical co-morbidities. We followed the recommendation of Chan et al and performed a two-stage procedure to make sure that there is no active infection at the time of revision implantation and also to allow for better wound care in this elderly patient.

4. Conclusion

This case report illustrates how polyethylene wear disease after TKA can manifest as a rapidly enlarging, massive cystic swelling in the posterior compartment of the leg. Our patient underwent a two stage surgery, excision of cyst followed by revision implantation which resulted in a good functional outcome.

Wear debris induced cyst or a pseudotumor mass must be included in the differential diagnosis of a swelling around the knee joint in post knee arthroplasty scenario.

Regular follow-up examination after TKA, with careful clinical and radiological assessment is critical for early

detection of occult polyethylene wear and prosthesis loosening.

Joint effusion and the subsequent synovial cyst formation should be considered a preceding sign of periprosthetic osteolysis, component wear, as well as prosthetic loosening.

5. Source of Funding

None.

6. Conflict of Interest

None.

References

1. Dirschl DR, Lachiewicz PF. Dissecting popliteal cyst as the presenting symptom of a malfunctioning total knee arthroplasty. Report of four cases. *J Arthroplasty*. 1992;7:37–41.
2. Moretti B, Patella V, Mouhsine E, Pesce V, Spinarelli A, Garofalo R. Multilobulated popliteal cyst after a failed total knee arthroplasty. *Knee Surg Sports Traumatol Arthrosc*. 2007;15:212–6.
3. Niki Y, Matsumoto H, Otani T, Yoshimine F, Inokuchi W, Morisue H. Gigantic popliteal synovial cyst caused by wear particles after total knee arthroplasty. *J Arthroplasty*. 2003;18:1071–5.
4. Chan YS, Wang CJ, Shin CH. Two-stage operation for treatment of a large dissecting popliteal cyst after failed total knee arthroplasty. *J Arthroplast*. 2000;15:1068–72.
5. Tofte JN, Holte AJ, Noiseux N. Popliteal (Baker's) Cysts in the Setting of Primary Knee Arthroplasty. *Iowa Orthop J*. 2017;37:177–80.
6. Akisue T, Kurosaka M, Matsui N, Yamaguchi M, Hasuda K, Bauer TW, et al. Paratibial cyst associated with wear debris after total knee arthroplasty. *J Arthroplast*. 2001;16:389–93.
7. Chang FY, Tseng KF, Chen WM, Huang CK, Chen TH, Lo WH. Metal-backed patellar component failure in total knee arthroplasty presenting as a giant calf mass. *J Arthroplast*. 2003;18:227–30.
8. Choi HR, Kwon YM. Calf swelling associated with a long-standing total knee arthroplasty. *J Orthop Sci*. 2015;20(1):209–12.
9. Huang TW, Wang CJ, Huang SC. Polyethylene-induced pes anserinus bursitis mimicking an infected total knee arthroplasty: a case report and review of the literature. *J Arthroplast*. 2003;18:383–6.
10. Chavda DV, Garvin KL. Failure of a polyethylene total knee component presenting as a thigh mass. *Clin Orthop Relat Res*. 1994;303:211–6.

Author biography

Muhammed Nazeer Senior Consultant

Rohith Raveendran Registrar

Bharat C Katragadda Fellow in Arthroplasty

Muhammed Ehsan N 3rd Year Resident

Cite this article: Nazeer M, Raveendran R, Katragadda BC, Ehsan N M. Huge calf swelling associated with a failed total knee replacement: A case report. *Indian J Orthop Surg* 2020;6(3):254–258.